

# In Motion Timer


60L - 61H - 120L  
In-Stock and Ready-to-Ship

*Rebuild Kit components includes the following (No Housing):*

## 1387577-RKAH

- 100L616AH. . . . Double Row Ball Bearing
- 11L615AH. . . . O-Ring
- 13L615AH. . . . Oil Seal
- 140L623AH. . . . Flange Drive, LH
- 158L816AH. . . . Locknut
- 159L816AH. . . . Lockwasher
- 265L653AH. . . . Spacer
- 29L617AH. . . . Retaining Ring
- 29L815AH. . . . O-Ring, Viton
- 2L617AH. . . . Retaining Ring, Nickel Plated
- 30L617AH. . . . Bearing Retainer
- 359L616AH. . . . Worm Shaft Bearing
- 3P140AH. . . . Knockout Rod Spring
- 50L623AH. . . . Adjusting Sleeve
- 51L623AH. . . . Drive Sleeve
- 53L623AH. . . . Worm
- 65L644AH. . . . Worm Gear Shaft
- 97L815AH. . . . O-Ring
- 99L616AH. . . . Bearing
- 9L617AH. . . . Retaining Ring

Housing  
71L643AH



Rebuild Kit - No Housing  
1387577-RKAH



**Call American Holt at 781-440-9993 for details.**

[sales@americanholt.com](mailto:sales@americanholt.com)

[www.americanholt.com](http://www.americanholt.com)

**American HOLT**  
*engineered savings*

**Notice:** All parts offered by American Holt are manufactured by or for American Holt and not by or for the original equipment manufacturer. Part numbers shown that are those of the original equipment manufacturer, if any, are used for references purposes only. American Holt is an independent supplier of quality replacement parts having no affiliation with any original equipment manufacturer. All prices are subject to change without notice.